

Page !

Item ID:

D3494-1

Revision ID:

Item Name:

Start Date:

Stub Cover 4/25/2011

QC:

Start Qty: 10.00

Required Date: 4/29/2011

Reg'd Qty: 10.00





Setup Start

Stop



Cust Item ID: Customer:

Tool ID

Approvals:

Reference:

Process Plan:

Date: Date:

Tooling:

Accept

SPC (Y/N):

Set Up/

Run Hours

Date: Date:

Tool#

Plan

Code

Run

Reject

Qty

Start



Stop

Reject

Number Stamp

Insp.

Sequence ID/ Work Center ID

Operation Description

Draw Nbr Revision Nbr

D3494

Rev D

100

Waterjet

FLOW CNC Waterjet

304.063

Memo

1-Cut as per Dwg

Dwg Rev Prog Rev:

0.00

0.00

B 11-4-75

Accept

Qty

2-Deburr if necessary

110

QC2-Inspect parts off machine FAI/FAIB

0.00

Memo

0.00

1811-4-06

Quality Control

Work Order ID 68881

Monday, April 25, 2011 8:38:34 AM

Item ID:

D3494-1

Revision ID:

Item Name:

QC:

4/25/2011

Stub Cover

Start Qty: 10.00 Req'd Qty: 10.00

Reference:

Start Date:

Approvals:

Process Plan:

Date:

Tooling:

0.00

0.00

0.00

Set Up/

Run Hours

2 would

Date:

SPC (Y/N):

Sequence ID/ Work Center ID

Required Date: 4/29/2011

120

Quality Control

130

Brake NC

Brake NC

Operation Description

QC8- Inspect parts - second check

Memo

Bend as per dwg

Memo

Memo

140

Quality Control

QC5- Inspect part completeness to step on W/O

Accept



Setup Start



Stop

Cust Item ID:

Customer:

Date:

Date:

Run Start

Stop



Tool ID

11/04/28

Tool# Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp





Work Order ID 68881

Monday, April 25, 2011 8:38:34 AM



Item ID:

D3494-1

Accept

Setup Start

Stop



Revision ID:

Item Name: Stub Cover

4/25/2011

Start Oty: 10.00

Reg'd Oty: 10.00

Cust Item ID:

Customer:

Reference:

Start Date:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

OC:

Required Date: 4/29/2011

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/

Work Center ID

144

Large Fab

Large Fab

Operation Description

Weld per dwg A/R S.S. rod Batch: M116577

Set Up/ **Run Hours**

Tool ID Tool # Plan

Accept Oty

Code

Reject Otv

Reject Number

Insp. Stamp

11.05.12

2- GRIND AS PER DWG

QC5- Inspect part completeness to step on W/O

0.00

QC10- Inspect visual per QSI004- ground welds

146

Quality Control

Memo

0.00

0.00

0.00

8 most 25

(HZ

147

Memo

0.00

S most 25

Quality Control

64:11 HOION J. HO. 000 1 NONO +1) omat. properties. 01:11 70478 12 Se-C-11 79 coq6 Run Hours Describition Work Center ID Reject Reject Idasay Tool # Plan do 105 (11 100 1 Operation Zednence ID :518(1 :(N/A) 3dS :916(1 ()() Tooling: 1)316: Date: Process Plan: (speaouddy SIBLE Run :ээнэлэгэЯ (national) Req'd Qiy: 10.00 Required Date: 4.29.2011 Cust liem ID: 00'01 310 Ems Start Date: 1102 52 1 dois 12 AL 1 ABIS Hem Anne: :(III moisivo II): mers duras recebr 1-1:01:01 Hem ID: INTEREST INC SCHOOL SEPTIME 10 miles Mork Order ID 68881

55/20/11 De 4 5/

omaty

months of agents of away and so agencies.

managaza radan - sa

Torrier A virterity

amory wit

024

Page 5



1888a (II 19b1O daoW

The 18 St & 110% C pade impungs

1-1615(1

recebi

00.0

000 0

Run Hours

/d 1 105

3. (1. V):

Tooling:

contain our room Part Lattin

Req'd Qty: 10.00

Required Date: 4.29.2015 Start Date: 1100 ST t

Reference:

заших шан

:(II noisi es)!

item ID:

Process Plan: Approvats

OC:

Operation

penalah tahil kendi sentangan hari seta Relense Description

Work Center ID Zedneuce ID.

mean

panner) superior

Date:

Date:

5t.50-1)

durers

dsuj

Aumber

Reject

Reject

Run

HEIS

dois

neis duiss

dossy

Tool # 1007

(11400T

ташовы)

:(II moff izu)

Date:

Date:


Picklist Print

Monday, April 25, 2011 8:38:31 AM

Work Order ID: 68881

Parent Item: D3494-1

Parent Item Name: Stub Cover



Start Date: 4/25/2011

Required Date: 4/29/2011

Start Qty: 10.00

Required Qty: 10.00

Comments:

IPP Rev:A New Issue 06-05-18 JLM

IPP rev B ecn 888 06.12.13 EC

add welding DD 10.03.03 verifie by:EC

chg design EC verified by:DD

IPP Rev:C

Ipp RevD ECN 10-555

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Otv	Qty Issued	Date Issued	Status	
M304S16GA		Purchased	No			100	sf	185.5000	0.72	7.578947	10,			
304/316 Sheet 063										1311-	4-25			

 Location
 Loc Qty
 Loc Code


 MAT020
 185.5


 117275
 185.5

The

75651

...





DART AEROSPACE LTD	Work Order: 6888
Description: STUB COUFR	Part Number: D3494~1
Inspection Dwg: 75494 Rev: D	Page 1 of 1

		ARTICLE			OTTE O		
	X	First Artic	cle x	Proto	otype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method o		omments
Y RUE,	- 010	,269	d		V 1802		
.368 4	, G(C)	,364	X		ν		
.706 7		768	7		V		
2528 4	- 010	2.500	*		V		
6.278 4	- 610.	6.773	7		V		
8.039 7		8.041	8		V		
8.437 1/2	- 010	8.446	X		PROW 30	2	
8.805 7	***************************************	8.810	4		P		
1.832 4		1.839	>		V		
3, 367 1		3,365	7		V		
3.604		3.608	×		V		
3.940 1/		3.938	8		V		
7.544 7	.010	7.549	7		V		
7.987 7	910	7.890	7		V		
9.317 7	clu	9.319	٨		8		-
11.149	. 010	11,156	V		8		
,660	010 -	,057	>		V		
	5					-	
		1					
ageured by		A codita of the					
easured by: B		Audited by:	0			proval:	
Date:	-4-24	Date:	70/40/11			Date:	